



BACKFLOW PREVENTION DEVICE TEST REPORT

No 9202

1601 Las Plumas Avenue, San Jose, CA 95133-1613
408/347-3533 Fax: 408/347-3416

RETURN NO LATER THAN

Job # 823071

RECEIVED ORCHARD SEP 04 2013

SERVICE ADDRESS: 1 Circle Star Way
DEVICE LOCATED: on Roof / Water Feature

RETURN TO: ACCT. NO. METER NO. Introna?

MAILING ADDRESS: Orchard Commercial 2055 Laurelwood Rd Ste #130 Santa Clara CA 95054
DEVICE INFORMATION: TYPE RG SIZE 1" MFG Watts MODEL: LF009M2BT SER. NO. 011291
TYPE OF SERVICE: [X] INDUSTRIAL [] DOMESTIC [] IRRIGATION [] FIRE

REPORT OF TEST RESULTS [X] PASS [] FAIL

Table with columns: REDUCED DOUBLE CHECK, REDUCED CHECK, ASSEMBLY RELIEF VALVE, PRESSURE VACUUM BREAKER, SHUT-OFF VALVE. Includes rows for INITIAL TEST, REPAIRS, and FINAL TEST.

THE ABOVE REPORT IS CERTIFIED TO BE TRUE:
INITIAL TEST BY [Signature] CERTIFIED TESTER NO. 10697 DATE 8-30-13
REPAIRED BY: DATE
FINAL TEST BY: CERTIFIED TESTER NO. DATE
COMMENTS: