

Phone: 800-436-6201 Fax: 925-609-6446



January 20, 2014,

County of San Mateo C/O Orchard Commercial Properties 2055 Laurelwood Road, Suite 130 Santa Clara, CA 95054

Phone: (408)955-1437

Email: sayala@orchardcommercial.com Cc: dkaiser@orchardcommercial.com Cc: vjimenez@orchardcommercial.com

Sonia Ayala, Property Manager Attn:

Re: 2014 Report of Annual Inspection of EBM Safety Equipment for the building located at:

2 Circle Star Way, San Carlos, CA

Date of Inspection: January 16, 2014

Inspection Expiration: January 16, 2015

Building Elevation: 4 Floors

Equipment Inspected: Mechanical Room (The total numbers indicate pieces of equipment inspected.)

Tie-back Anchors (on screen wall post)

5 Safety Shackles

1 Life Line

Main Roof

Tie-back Anchors

Non Equipment Inspected

- **OPOS** (Operating Procedure Outline Sheet)
- \checkmark Safety Signage (Lynn Safety's Red Decal Sticker)
- \checkmark Danger Zone Line
- Danger Zone Safety Signage

SIT No. 29 **EQUIPMENT INSPECTED** APPROVED FOR USE Accredited by CA Dept of Occupational Safety & Health State of California

Accredited Scaffold, Inspection & Testing

Agency

Lynn Safety, Inc.

No deficiencies were found during our visual Inspection and equipment used for window cleaning is Ok for use.

Continued next page . . .

RE: One Circle Star Way, San Carlos, CA - Annual Inspection Report 2014

Comments:

1. Some Tie-back anchors were spray galvanized.

The next Annual Inspection of this equipment should be during <u>January 2015</u>. We will include your building in our tracking files for Annual Inspections. Each year a reminder card or an e-mail will be sent to you the month before the Inspection is due with a pre-scheduled date.

Please give us a call if you should have any questions upon review of this Annual Inspection Report.

Respectfully,

Steven P. Lynn Jr. Operations Manager